

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	5	((electrical adj overstress) (electrical adj over adj stress) eos) same firewire	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/01/17 11:34
S2	57	((electrical adj overstress) (electrical adj over adj stress) eos) and firewire	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/01/17 11:35
S3	3613	((electrical adj overstress) (electrical adj over adj stress) eos) same (cable connector)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/01/17 11:41
S4	4	((electrical adj overstress) (electrical adj over adj stress) eos) same (cable connector) same programmable	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/01/17 11:41
S5	121	((electrical adj overstress) (electrical adj over adj stress) eos) same programmable	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/01/17 11:42
S6	4	((electrical adj overstress) (electrical adj over adj stress) eos) same programmable near3 (threshold detector voltage clamp\$3 trigger\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/01/17 11:42
S7	105	((electrical adj overstress) (electrical adj over adj stress) eos) and programmable near3 (threshold detector voltage clamp\$3 trigger\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/01/17 11:43
S8	7	((electrical adj overstress) (electrical adj over adj stress) eos) same programmable near3 (detect\$3 monitor\$3 sens\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/01/17 11:55